

MI Collimator Status

I. Kourbanis

09/27/07

Status

- All the 4 secondary collimators have been installed.
 - All the LCW and bus modifications have been completed
 - The whole MI-30 area is being pumped down
 - Testing of the collimator motors and instrumentation is underway
- All shielding masks have been installed except the concrete shielding wall at 305.

Col2(303)



COL3(307)



COL4 (309)



LCW Modifications 301-305



Steel-Marble mask (3)



Steel-concrete Mask (3)

