

QIE–Testing Work List

- 1) DNL Ch. B with current injection
(high stats, whole dynamic range)**
- 2) DNL Ch. A
(check theory of ref. ladder at low peds)**
- 3) Investigate wandering caps with
input disconnected at HPD**
- 4) Investigate link circuit to fix ch. A**